

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-023053**Date Inspected:** 04-Apr-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Xu Le Feng**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Components**Summary of Items Observed:**

On this date Caltrans Office of Structural Materials Quality Assurance Inspector, Sandeep Kumar (QA) was present during the times noted above for observations relative to the work being performed.

BAY#10

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No. 08728

Ultrasonic Testing (UT)

This QA inspector performed UT of the area previously tested and accepted by ZPMC Quality Control personnel.

This QA Inspector generated an UT report for this date. The member is identified as OBG Component. The weld designation reviewed as follows:

BIKE PATH

BK009A3-001-009

BK009A5-001-010

This QA Inspector observed the following work in progress

Shielded Metal Arc Welding (SMAW):

Weld joint #010 located on Bike Path BK14A3-001. Welder is identified as 040582. ZPMC Quality Control (QC) Inspector is identified as Yu Zhi Lai. The welding variables recorded by QC appeared to comply with the

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

WPS-B-T-2211-Tc-U4b. (See attached photo)

Weld joint #008 located on Bike Path BK14A5-001. Welder is identified as 057220. ZPMC Quality Control (QC) Inspector is identified as Yu Zhi Lai. The welding variables recorded by QC appeared to comply with the WPS-B-T-2211-Tc-U4b.

Weld joint #002 located on Bike Path BK14A3-001. Welder is identified as 040581. ZPMC Quality Control (QC) Inspector is identified as Yu Zhi Lai. The welding variables recorded by QC appeared to comply with the WPS-B-T-2211-Tc-U4b.

Weld joint #002 located on Bike Path BK14A5-001. Welder is identified as 500363. ZPMC Quality Control (QC) Inspector is identified as Yu Zhi Lai. The welding variables recorded by QC appeared to comply with the WPS-B-T-2211-Tc-U4b.

BAY#11

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No. 08729

Ultrasonic Testing (UT)

This QA inspector performed UT of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The member is identified as OBG Component. The weld designation reviewed as follows:

BIKE PATH

BK011A1-001-044

This QA Inspector observed the following work in progress

Shielded Metal Arc Welding (SMAW):

Weld joint #007 located on Traveler Rail 3011TR1-001. Welder is identified as 046704. ZPMC Quality Control (QC) Inspector is identified as Wang Chuang Xin. The welding variables recorded by QC appeared to comply with the WPS-B-P-2112.

Weld joint #013 located on Traveler Rail 3011TR1-001. Welder is identified as 044541. ZPMC Quality Control (QC) Inspector is identified as Wang Chuang Xin. The welding variables recorded by QC appeared to comply with the WPS-B-P-2112.

Weld joint #010 located on Traveler Rail 3011TR1-001. Welder is identified as 040611. ZPMC Quality Control (QC) Inspector is identified as Wang Chuang Xin. The welding variables recorded by QC appeared to comply with the WPS-B-P-2112.

Weld joint #018 located on Traveler Rail 3011TR1-001. Welder is identified as 046269. ZPMC Quality Control (QC) Inspector is identified as Wang Chuang Xin. The welding variables recorded by QC appeared to comply with the WPS-B-P-2112. (See attached photo)

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No Relevant Conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Thomas Ho - 15002048250, who represents the Office of Structural Materials for your project.

Inspected By:	Kumar,Sandeep
----------------------	---------------

Quality Assurance Inspector

Reviewed By:	Clifford,William
---------------------	------------------

QA Reviewer
